



FLUO TP

THE ONLY PAINT THAT DOES NOT CONTAIN CARCINOGENIC, MUTAGENIC, OR TOXIC **COMPONENTS FOR REPRODUCTION**

PAINTS THAT RESPECT MEN AND THE **ENVIRONMENT**

100% USAGE GUARANTEE, NO WASTE

UNIQUE AND PATENTED SAFETY CAP:

- The only locking cap
- A particularly robust safety cap (a full aerosol dropped from a height of 1.50m will remain intact)
- No contact with the paint

CAN BE USED UP TO -15°C

VERY BRIGHT MARKING AND COVERING CAPACITY IN A SINGLE PASS, HIGHLY **FLUORESCENT**

ONLY 2 PICTOGRAMS!











7 COLOURS AVAILABLE















INSTRUCTIONS FOR USE











- **1** Before use: Shake vigorously (balls must be clearly audible)
- 2. Unlock the aerosol by turning left the safety cap
- 3 Use Fluo TP® « head down » about 10cm from the support
- 4 . After use, purge « head up » to clean out the valve and the diffuser
- 5 Lock the aerosol by turning right the safety cap

PROPERTIES

Coverage capacity: From 2 to 4m², depending on covering power and to the nature of the support (colour, porosity)

Autonomy: 100 meters to have maximal coverage. Allows to realize 150 to 200 meters of marking within the speed of application and of covering wished.

Drying time: About 10 minutes at 20°C

Ideal storage between 15 to 25°C, do not freeze

Shelf life: 4 years warranty

Usable with the gun handle and the one-wheel applicator

HEATH AND SAFETY:

Consult our free safety data sheets on our website www.soppec-inc.com

No paint mist or drips during use GHS labelling with two pictograms







Carton **Box**



Palette Nimp15 100 x 120 cm



76 boxes per pallet of 12 aerosols





SAFETY CAP

FLUO TP is fitted with the patented Soppec ${}^{ ext{ iny TP}}$ safety cap. The unique design of this cap gives it the following advantages :

- · Protection against accidental tripping during transport or handling
- Protection of the user's hands against painting projections
- Easy to use
- The strongest safety cap on the market: No break when a full aerosol falls 1.50m (Test carried out on asphalt)
- A fine and precise spray which allows the realization of clear markings
- Cap denotes colour of the paint.

GENERAL CONDITIONS

- Do not expose to temperatures above 50°C
- Keep away from sources of ignition, heat and sunlight
- Do not smoke
- Do not pierce even after use the aerosol
- Do not burn even after use the aerosol