



PRO MARKER

THE ONLY PAINT THAT DOES NOT CONTAIN CARCINOGENIC, MUTAGENIC, OR TOXIC **COMPONENTS FOR REPRODUCTION**

PAINTS THAT RESPECT MEN AND THE **ENVIRONMENT**

100% USAGE GUARANTEE, NO WASTE

UNIQUE AND PATENTED SAFETY CAP:

- The only locking cap
- A particularly robust safety cap (a full aerosol dropped from a height of 1.50m will remain intact)
- No contact with the paint

CAN BE USED UP TO -15°C

PARTICULARLY GOOD COVERING **POWER**

ONLY 2 PICTOGRAMS!











6 COLOURS AVAILABLE













INSTRUCTIONS FOR USE











- 1. Before use: Shake vigorously (balls must be clearly audible)
- 2. Unlock the aerosol by turning left the safety cap
- 3. Use PRO MARKER ® « head down » about 10cm from the support
- 4. After use, purge « head up » to clean out the valve and the diffuser
- 5. Lock the aerosol by turning right the safety cap

HEATH AND SAFETY:

Consult our free safety data sheets on our website www.soppec-inc.com

No paint mist or drips during use GHS labelling with two pictograms








Carton **Box**



Palette Nimp15 100 x 120 cm



76 boxes per pallet of 12 aerosols

PROPERTIES

Marking duration: Over 12 months depending on the application conditions and surfaces, high resistance to weathering and UV rays.

Drying time: About 5 minutes at 20°C

Ideal storage between 15 to 25°C, do not freeze

Shelf life: 4 years warranty

Usable with the gun handle and the one-wheel applicator



SAFETY CAP

PRO MARKER is fitted with the patented Soppec ${\rm ~TP}$ safety cap. The unique design of this cap gives it the following advantages:

- Protection against accidental tripping during transport or handling
- Protection of the user's hands against painting projections
- Easy to use
- The strongest safety cap on the market: No break when a full aerosol falls 1.50m (Test carried out on asphalt)
- A fine and precise spray which allows the realization of clear markings
- Cap denotes colour of the paint.

GENERAL CONDITIONS

- Do not expose to temperatures above 50°C
- Keep away from sources of ignition, heat and sunlight
- Do not smoke
- Do not pierce even after use the aerosol
- Do not burn even after use the aerosol