



S-MARK FLUO

THE ONLY PAINT THAT DOES NOT CONTAIN CARCINOGENIC, MUTAGENIC, OR TOXIC COMPONENTS FOR REPRODUCTION

UNIQUE AND PATENTED SAFETY CAP :

- The only locking cap
- A particularly robust safety cap (a full aerosol dropped from a height of 1.50m will remain intact)
- No contact with the paint

PAINTS THAT RESPECT MEN AND THE ENVIRONMENT

100% USAGE GUARANTEE, NO WASTE

CAN BE USED UP TO -15°C

GOOD MARKING DURATION EVEN ON WET SURFACES

ONLY 3 PICTOGRAMS !



8 COLOURS AVAILABLE



INSTRUCTIONS FOR USE



- 1 . Before use : Shake vigorously (balls must be clearly audible)
- 2 . Unlock the aerosol by turning left the safety cap
- 3 . Use S-MARK « head down » about 10cm from the support
- 4 . After use, purge « head up » to clean out the valve and the diffuser
- 5 . Lock the aerosol by turning right the safety cap

PROPERTIES

Coverage capacity : From 2 to 4m², depending on covering power and to the nature of the support (colour, porosity)

Autonomy : 100 meters to have maximal coverage. Allows to realize 150 to 200 meters of marking within the speed of application and of covering wished..

Drying time : About 10 minutes at 20°C

Ideal storage between 15 to 25°C, **do not freeze**

Shelf life: 4 years warranty

Usable with the gun handle and the one-wheel applicator

HEALTH AND SAFETY :


Consult our free safety data sheets on our website www.soppec-inc.com

No paint mist or drips during use


GHS labelling with two pictograms



Carton
Box



Pallet Nimp15
100 x 120 cm



76 boxes per pallet of
12 aerosols



SAFETY CAP

S-MARK is fitted with the patented Soppec «TP» safety cap. The unique design of this cap gives it the following advantages :

- Protection against accidental tripping during transport or handling
- Protection of the user's hands against painting projections
- Easy to use
- The strongest safety cap on the market : No break when a full aerosol falls 1.50m (Test carried out on asphalt)
- A fine and precise spray which allows the realization of clear markings
- Cap denotes colour of the paint.

GENERAL CONDITIONS

- Do not expose to temperatures above 50°C
- Keep away from sources of ignition, heat and sunlight
- Do not smoke
- Do not pierce after use
- Do not burn after use